Adapted versus Projected Machining Centers Energy Consumption for MQL Technique

Augusto Dttmann¹, Jefferson de Oliveira Gomes²

¹Department of Mechanical Engineering, Aeronautics Institute of Technology (ITA), Marechal Eduardo Gomes 50, São José dos Campos 12228-900, Brazil (augusto@ita.br) ORCID 0000-0003-2264-8572; ²Department of Mechanical Engineering, Aeronautics Institute of Technology (ITA), Marechal Eduardo Gomes 50, São José dos Campos 12228-900, Brazil (gomes@ita.br) ORCID 0000-0002-6004-799X

Abstract

Cutting fluid application is a vital technique to achieve the expected result in most machining processes. However, besides having a high cost, the cutting fluid application also represents a risk to the environment due the oil chemical characteristics. The Minimum Quantity Lubrication (MQL) is an alternative when looking for reduction of oil consumption and a more environmentally friendly process. A literature review has shown that many predictive models of machine tool power consumption do not consider the consumption of the required air compressor in MQL. This paper's motivation was testing these models to predict the energy consumption. It was observed that the amount of consumed energy in the cutting is lower when compared to the consumption of basic components of the machining center in both cases. Using the MQL, the tool life showed a decrease. However, it allows the feed to increase and reduces the energy consumption.

Author Keywords. Manufacturing, Machining, MQL, Energy.

Type: Research Article ∂ Open Access Ø Peer Reviewed ⓒ CC BY

1. Introduction

Manufacturing is the most influential industry sector in the world economy (Hamran et al. 2020). Among the production processes, machining stands out as being one of the main discrete manufacturing process (Sharma, Dogra, and Suri 2009; Dttmann and Gomes 2019). In the industry, the machining process is planned to provide the best quality or the lowest cost possible (Umbrello, Micari, and Jawahir 2012).

Machining features high financial and environmental costs (Sharma, Dogra, and Suri 2009; Hamran et al. 2020). Over the decades, quality requirements, increased productivity and development of new tools have been the object of research studies (Fratila and Caizar 2012). Studies show that one of the main financial costs of machining is the application of cutting fluid, which can correspond up to 20% of the total cost (Ekinovic, Prcanovic, and Begovic 2015; Klocke and Eisenblätter 1997). In addition, chemical additives, applied with the intention to reduce the bacteria growth in the cutting fluids, can cause damage to human health and environmental problems in disposal (Khunt et al. 2020).

It is currently possible to identify an increase in studies with the aim of developing a more sustainable process (Fratila and Caizar 2012; Gaurav et al. 2020; Sarikaya and Güllü 2014). This new direction of research is motivated by the increase in environmental regulations and the increasing cost pressure in the manufacturing industry (Fratila and Caizar 2012).

The Minimum Quantity Lubrication (MQL) is an alternative when looking for reduction of oil consumption and a more environmentally friendly process (Gaurav et al. 2020; Hamran et al.

2020). Furthermore, there are authors who defend the improvement of machining force, tool life increase and energy consumption decrease due to the withdrawal of the high pressure pump from the flood system, although there are divergences.

This paper aims to study the energy consumption in a comparative manner between one technique in two machining center, one adapted for MQL and another center designed to use the technique. During the study, tool life and cutting forces were also measured. The machining process chosen was the through-hole in gray cast iron.

2. Materials and Methods

The tests in this paper were performed according to the flowchart presented in Figure 1.



Figure 1: Flowchart test

For the definition of the parameters, a preliminary test was carried out. With the parameters defined, machining was carried out until the end of the tool's life in the three study conditions. During the machining process, the following data were monitored: tool life, machining force, energy consumption and machine power.

2.1. Machining center

For tests with adapted MQL, the ROMI D800 was used with a Bielomatik 1 channel system. The tests with designed MQL were performed on the GROB G550.





(a) (b)
 Figure 2: (a) Bielomatik single channel adapted in ROMI D800. (b) GROB Machining center GROB G550

2.2. Tool and work material

The material used for testing was gray cast iron DIN GG 25 with 182 HB, this material is used in the manufacture of motors and gears.

All specimens were milled to 380x240x37mm dimensions to ensure perpendicularity to the machine axis (Figure 3 (a) and Figure 3 (b)).





(a) (b) Figure 3: (a) Raw specimen. (b) Milled specimen for testing

2.3. Parameters and tool

In order to define machining parameters for drilling operation, dry tests were performed on the Romi D800. The selected parameters are shown in Table 1.



Figure 4: Criterion for defining end of tool life. Adapted from Dolinšek, Šuštaršič, and Kopač (2001)

Vc [m/min]	f [mm/rot]
110	0.3
110	0.4
140	0.3
140	0.4

 Table 1: Cutting parameters

Drilling operations were carried out with carbide drills, 13.5 mm diameter, 140° tip angle and TiAlN coated by Mapal. The tool's life criteria adopted was average flank wear VB(av)=0.2 mm, maximum flank wear VB(max)=0.3 mm, according to Rahim and Sasahara (2011). The measuring point on the drill is shown in Figure 4.

All drills were photographed in the new state and every specimen were machined. The images were captured with a JVC TK-C1380 video camera coupled to a Wild M3C Type-S microscope. Each drill was tagged to identify the edges. The wear was measured on both flanks.

2.4. Machining force

Machining forces were measured by using Kistler's piezoelectric platform (Figure 5). For the acquisition of the machining force the data were collected with the platform while three holes were made. In order to monitor the increase in machining force with the tool wear, the force measurements were performed at each stop of wear measurement and compared with the force measured with the drills in new state. These measurements were taken every 30 holes. For each acquisition round, a new file was created in the system's interface software Dynoware Type 2825-D-02 (Figure 6). To ensure a wide range of different load intensities, all acquisitions were performed with a measuring range of 4000 N per amplifier channel.



Figure 5: Kistler's piezoelectric platform



Figure 6: Software interface Dynoware Type 2825-D-02

2.5. Energy consumption

The required power demand was measured by using a Mult-K 120 KRON power meter and a digital magnitude transducer. LabView, which was developed in the laboratory, was used to read and organize the collected data.

The models evaluated for energy consumption are listed in Table 2. This table was adapted from Balogun and Mativenga (2013).

Mori et al. (2011) $E = P1(T1 + T2) + P2T2 + P3T3$ (1)E = total energy consumption [Wh];P1, P2, P3 = constant power, idle and cut [W], respectively; T1, T2, T3 = corresponding time of the powers.(2)Diaz, Helu, and Dornfeld (2010) $E = P. \Delta t = (Pcut + Pair). \Delta t$ (2)E = total energy consumption [Wh];P1 = total power demand [W]; Δt = machining time [h];Pcut = cut power [W];Pempty = power demand operating on empty [W](3)He et al. (2012) $E = total energy consumption [Wh];P1 = total power demand operating on empty [W](3)He et al. (2012)E = Spindle + E_{feed} + E_{uo} + E_{cool} + E_{un}tsi tci m t/iE = fus_f Pmdt + fue_f Pcdt + \sum_{l=1} f_{lff} Pldt + P_{tool} tool + P_{cool} \Delta t_{cool} + (P_{servo} + P_{air})\Delta t(3)Pc = cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Pcool = power of thecooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; Ptool = power of thecooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; Pcool = power of thecooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; Pcool = power ofthe cooling system; tb = machine time [h]; \Delta t(4)Balogun andMativenga (2013)E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + k\dot{v})tc(4)E = total energy consumed [W]; Pb = constant power demand [W]; Pcool = powerof the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar =empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated valueaccording to the material [k]/cm³];\dot{v} = material remove rate [mm³/s].Aramcharoen andMativenga (2014)Etotal = Energy consumed by the machine in the on state without splindle and feed movement;$	Author	Model	
E = total energy consumption [Wh];P1, P2, P3 = constant power, idle and cut [W], respectively; T1, T2, T3 = corresponding time of the powers.Diaz, Helu, and Dornfeld (2010) $E = P. \Delta t = (Pcut + Pair). \Delta t$ (2)E = total energy consumption [Wh];P = total power demand [W]; Δt = machining time [h];Pcut = cut power [W];Pempty = power demand operating on empty [W](3)He et al. (2012) $E = Espindle + E_{feed} + E_{sus} + E_{cool} + E_{sut}$ total total tot	Mori et al. (2011)	E = P1(T1 + T2) + P2T2 + P3T3	(1)
T1, T2, T3 = corresponding time of the powers.Diaz, Helu, and Dornfeld (2010) $E = P. \Delta t = (Pcut + Pair). \Delta t$ (2)E = D. $\Delta t = (Pcut + Pair). \Delta t$ (2)E = total energy consumption [Wh]; P = total power demand [W]; Δt = machining time [h]; Pcut = cut power [W]; Pempty = power demand operating on empty [W](3)He et al. (2012) $E = E_{spindle} + E_{teed} + E_{tool} + E_{cool} + E_{set}$ tot tot power [W]; Pmdt + $\int ter Pcdt + \sum tei \int tr/ Pidt + Ptool tool + Pcool \Delta t_{cool} + (Pservo + Pair)\Delta t$ (3)Pc = cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Pcool = power of the cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial and final spindle time [h]; tci e tcf = inicial and final cut time [h]; Δt pump = pump dirve range;Balogun and Mativenga (2013) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + kv)tc$ E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tr = cutting time [h]; k = specific energy required, tabulated value according to the material [kJ/cm³]; v = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)Etotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Eucu = Energy consumed in the cut; Efeed = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed		E = total energy consumption [Wh];P1, P2, P3 = constant power, idle and cut [W], respe	ctively;
Diaz, Helu, and Dornfeld (2010) $E = P. \Delta t = (Pcut + Pair). \Delta t$ (2)E = total energy consumption [Wh];P = total power demand [W]; Δt = machining time [h];Pcut = cut power [W];Pempty = power demand operating on empty [W](3)He et al. (2012) $E = E_{spindle} + E_{feed} + E_{uos} + E_{cool} + E_{set}$ (3)He et al. (2012) $E = E_{spindle} + E_{feed} + E_{uos} + E_{cool} + E_{set}$ (3)He et al. (2012) $E = E_{spindle} + E_{feed} + E_{uos} + E_{cool} + E_{set}$ (3)He et al. (2012) $E = E_{spindle} + E_{feed} + E_{uos} + E_{cool} + E_{set}$ (4)He et al. (2012) $E = Cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Ptool = power of thecooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi et sf = incial and finalspindle time [h]; tci e tcf = inicial and final cut time [h]; \Delta t pump = pump dirve range;Balogun andMativenga (2013)E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + kiv) tc(4)E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand instandby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = powerof the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar =empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated valueaccording to the material [k]/cm3]; \dot{\nu} = material remove rate [mm3/s].Aramcharoen andMativenga (2014)Etotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement;Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement;Eul = Energy consumed in the $		<u>T1, T2, T3 = corresponding time of the powers.</u>	
Dornfeld (2010)E = total energy consumption [Wh];P = total power demand [W]; Δt = machining time [h];Pcut = cut power [W];Pempty = power demand operating on empty [W]He et al. (2012) $E = E_{spindle} + E_{feed} + E_{tool} + E_{sec}$ tsi $E = \int_{tsf} Pmdt + \int_{tcf} P_c dt + \sum_{i=1} \int_{trf} P_i dt + P_{tool} L_{tool} + P_{cool} \Delta t_{cool} + (P_{servo} + P_{air}) \Delta t$ (3)Pc = cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Pcool = power of the cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; Pcool = power of the cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial and final spindle time [h]; tci e tcf = inicial and final cut time [h]; Δt pump = pump dirve range;Balogun and Mativenga (2013) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + k\dot{v})tc$ Aramcharoen and Mativenga (2014) $E = total energy consumed [W]; Pe mathine time [h]; tr = time of machine to be machined [h]; tar =empty operating time [h]; tc = cutting time [h]; tr = time of machine to be machined [h]; tar =empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated valueaccording to the material [kJ/cm³];\dot{v} = material remove rate [mm³/s].Aramcharoen andMativenga (2014)Eidle = Energy consumed by the machine in the on state without splindle and feed movement;Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement;Etool = Energy consumed in the cut;Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by thew = mining the splice or cutter; Epump = Energy consumed by them = mining the splice or cutter; Epump = Energy consumed by them = mining the splice or cutter; Epump = Energy consumed by them = mining to the table or cutter; Epump = Energy cons$	Diaz, Helu, and	$\boldsymbol{E} = \boldsymbol{P}. \ \Delta \boldsymbol{t} = (\boldsymbol{P}\boldsymbol{c}ut + \boldsymbol{P}\boldsymbol{a}i\boldsymbol{r}). \ \Delta \boldsymbol{t}$	(2)
E = total energy consumption [Wh];P = total power demand [W]; Δt = machining time [h];Pcut = cut power [W];Pempty = power demand operating on empty [W]He et al. (2012) $E = S_{spindle} + E_{feed} + E_{teel} + E_{cool} + E_{set}$ (3)He et al. (2012) $E = S_{spindle} + E_{feed} + E_{teel} + E_{cool} + E_{set}$ (3) $E = \int_{tsf} P_m dt + \int_{tcf} P_c dt + \sum_{i=1} \int_{tff} P_i dt + P_{tool} \Delta_{tcool} + (P_{servo} + P_{air}) \Delta t$ (3)Pc = cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Pcool = power of the cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial and final spindle time [h]; tci e tcf = inicial and final cut time [h]; Δ tpump = pump dirve range;Balogun and Mativenga (2013) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + k\dot{v})tc$ (4)E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated value according to the material [k]/cm ³]; \dot{v} = material remove rate [mm ³ /s].Aramcharoen and Mativenga (2014)ETotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Ecut = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the with et all ender splite to the splite and feed movement; Energy consumed when moving the table or cutter; Epump = Energy cons	Dornfeld (2010)		
He et al. (2012) $E = E_{spindle} + E_{feed} + E_{tool} + E_{set}$ (3)He et al. (2012) $E = E_{spindle} + E_{feed} + E_{tool} + E_{set}$ (3) tsi tci m tfi $E = \int_{tsf} P_m dt + \int_{tcf} P_c dt + \sum_{i=1} \int_{tff} P_i dt + P_{tool} t_{tool} + P_{cool} \Delta t_{cool} + (P_{servo} + P_{oir}) \Delta t$ (3)Pc = cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Pcool = power of the cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial and final spindle time [h]; tci e tcf = inicial and final cut time [h]; Δ tpump = pump dirve range;Balogun and Mativenga (2013) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + k\dot{v})tc$ E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated value according to the material [k]/cm ³]; \dot{v} = material remove rate [mm ³ /s].Aramcharoen and Mativenga (2014)ETotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Ecut = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the energy consumed by the machine in the or state.		E = total energy consumption [Wh];P = total power demand [W]; Δt = machining time [h]];Pcut =
He et al. (2012) $E = E_{spindle} + E_{feed} + E_{twol} + E_{cool} + E_{set}$ (3)Is the two the		cut power [W];Pempty = power demand operating on empty [W]	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	He et al. (2012)	$E = E_{spindle} + E_{feed} + E_{tool} + E_{cool} + E_{set}$	(3)
$E = \int tsf Pmdt + \int tcf Pcdt + \sum_{i=1} \int trf P_i dt + P_{tool} t_{tool} + P_{cool} \Delta t_{cool} + (P_{servo} + P_{air}) \Delta t$ Pc = cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Pcool = power of the cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial and final spindle time [h]; tci e tcf = inicial and final cut time [h]; \Delta tpump = pump dirve range;Balogun and Mativenga (2013) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + k\dot{v})tc$ E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated value according to the material [kJ/cm³]; \dot{v} = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)Etotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Ecut = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the energy consumed by the machine to be cutter; Epump = Energy consumed by the energy consumed by the machine table or cutter; Epump = Energy consumed by the energy co		tsi tci m tfi	
$P_{air} \Delta t$ Pc = cut power [W]; Pf = feed power [W];Ptool = tool change power [W]; Pcool = power of the cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial and final spindle time [h]; tci e tcf = inicial and final cut time [h]; $\Delta tpump = pump dirve range;$ Balogun and Mativenga (2013)(4) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + kv)tc$ E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h];k = specific energy required, tabulated value according to the material [kJ/cm³]; v = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)Etotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the energy consumed by the energy consumed by the energy consumed by the energy consumed by the machine in the prome cutter; Epump = Energy consumed by the energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the energy consu		$E = \int_{tsf} P_m dt + \int_{tcf} P_c dt + \sum_{i=1} \int_{tff} P_i dt + P_{tool} t_{tool} + P_{cool} \Delta t_{cool} + (P_{servo} + P_{cool} \Delta t_{cool}) + (P_{servo} + P_{cool} \Delta t_{cool$	
Pc = cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Pcool = power of the cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial and final spindle time [h]; tci e tcf = inicial and final cut time [h]; Δ tpump = pump dirve range;(4)Balogun and Mativenga (2013) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + kv)tc$ (4)E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h];k = specific energy required, tabulated value according to the material [kJ/cm³]; v = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)Etotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed in tool change; Espindle = Energy consumed by the machine in the on state without splindle and feed movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the uter function the cutter; Energy consumed when moving the table or cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the uter function the cutter; Epump = Energy consumed by the 		$P_{\text{air}}\Delta t$	
cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial and final spindle time [h]; tci e tcf = inicial and final cut time [h]; Δ tpump = pump dirve range;Balogun and Mativenga (2013)		Pc = cut power [W]; Pf = feed power [W]; Ptool = tool change power [W]; Pcool = powe	r of the
spindle time [h]; tci e tcf = inicial and final cut time [h]; Δ tpump = pump dirve range;Balogun and Mativenga (2013) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + k\u03c6) tc$ (4)E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated value according to the material [kJ/cm³]; $\dot{\nu}$ = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)ETotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the energy consumed by the balle or cutter; Epump = Energy consumed by the energy consumed by the moving the table or cutter; Epump = Energy consumed by the		cooling pump [W]; Pservo = servo power [W]; Pair = air power [W]; tsi e tsf = incial a	nd final
Balogun and Mativenga (2013)(4)E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + kv)tc(4)E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h];k = specific energy required, tabulated value according to the material [kJ/cm³];v = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)ETotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Ecut = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed when moving the table or cutter; Epump = Energy consumed by the um = fluit.		spindle time [h]; tci e tcf = inicial and final cut time [h];∆tpump = pump dirve range;	
Mativenga (2013) $E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + kv)tc$ E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h];k = specific energy required, tabulated value according to the material [kJ/cm³];v = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)ETotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Ecut = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the	Balogun and		(4)
E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power demand in standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h];k = specific energy required, tabulated value according to the material [kJ/cm³]; \dot{v} = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)ETotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the material is a spin to be table or cutter; Epump = Energy consumed by the material is a spin table or cutter; Epump = Energy consumed by the	Mativenga (2013)	$E = Pbtb + (Pb + Pr)tr + Pairtair + (Pb + Pr + Pref + k\dot{v})tc$	
standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool = power of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated value according to the material [kJ/cm³]; $\dot{\nu}$ = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)ETotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Ecut = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed when moving the table or cutter; Epump = Energy consumed by the		E = total energy consumed [W]; Pb = constant power demand [W]; Pr = power den	nand in
of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]; tar = empty operating time [h]; tc = cutting time [h]; k = specific energy required, tabulated value according to the material [kJ/cm³]; \dot{v} = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)Etotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the		standby mode (door closed) [W]; Pempty = cutting power operating in empty [W]; Pcool =	= power
empty operating time [n]; tc = cutting time [n]; k = specific energy required, tabulated value according to the material [kJ/cm³]; \dot{v} = material remove rate [mm³/s].Aramcharoen and Mativenga (2014)ETotal = Eidle + Etool + Espindle + Ecut + Efeed + EfluidEidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the movement is table or cutter; Epump = Energy consumed by the		of the cooling system; tb = machine time [h]; tr = time of machine to be machined [h]	i]; tar =
Aramcharoen and Mativenga (2014) ETotal = Eidle + Etool + Espindle + Ecut + Efeed + Efluid Eidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the		empty operating time [n]; it = cutting time [n]; $k = specific energy required, tabulate$	u value
Mativenga (2014) ETotal = Eidle + Etool + Espindle + Ecut + Efeed + Efluid Eidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the	Aramcharoen and		
Eidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the	Mativenga (2014)	ETotal = Eidle + Etool + Espindle + Ecut + Efeed + Efluid	
Eidle = Energy consumed by the machine in the on state without splindle and feed movement; Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the	(2011)		
Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement; Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the		Eidle = Energy consumed by the machine in the on state without splindle and feed mov	ement;
Ecut = Energy consumed in the cut; Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the		Etool = Energy consumed in tool change; Espindle = Energy consumed by spindle movement;	
Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed by the		Ecut = Energy consumed in the cut;	
		Efeed = Energy consumed when moving the table or cutter; Epump = Energy consumed	l by the
cutting fluid pump.		cutting fluid pump.	

Table 2: Energy consumption forecasting models

3. Results and Discussion

3.1. Tool life and force

Tool life in the four established machining conditions was shorter with adapted MQL when compared to a machine designed for MQL. Flank wear was more pronounced in this condition (Figure 7).

One of the benefits of using MQL is a minor flank wear when compared to dry machining and flood (Dhar, Kamruzzaman, and Ahmed 2006; Özbek and Saruhan 2020). However, although the technique allows for an increase in tool life, it is important to evaluate how the application will be made, since adapted systems may have their efficiency reduced.

The MQL system utilized in the adaptation was single channel with internal feed. As the production of aerosol occurs in the tank before entering the spindle and thus being taken to the tip of the tool, leaks occur in the adaptations along the path. Consequently, there is less efficient flow in the adapted system and this loss implies poor lubrication. Thus, the shorter tool life observed in conditions with adapted MQL may have the lack of lubrication as a factor, since the application in the cutting region to cool and lubricate allows to increase the tool life (Hamran et al. 2020; Ravi, Gurusamy, and Mohanavel 2020).

The machining force was greater with the adapted MQL system when compared to the designed system. As expected, the force increased with the cutting distance due the increased flank wear observed (Figure 8).



Figure 7: Flank wear for MQL adapted and projected



Figure 8: Feed Force x Cutting Length

When analyzing the shear curve, it is possible to verify the same behavior in the flank wear curve. The difference between adapted and projected is more pronounced in condition 4, which corresponded to a greater difference in tool wear, especially at life end.

This behavior is in agreement with the shape of the measured wear, since an increase in the flank wear generates an increase in the friction of the tool/workpiece, increasing the cutting force (Machado et al. 2011).

3.2. Energy

The prediction of energy consumption models came closer to the measured value with flooding (Figure 9). The theoretical value was calculated according to the works of the

respective authors (Balogun and Mativenga 2013; Aramcharoen and Mativenga 2014; Diaz, Helu, and Dornfeld 2010; He et al. 2012; Mori et al. 2011).



Figure 9: Energy consumption: prediction and measurement

The values were measured to make three holes with a length of 37 mm. The energy consumption per hole, for each machining condition, is shown in Figure 10. In this assessment, the energy consumption of the compressed air was not considered, since there is no such prediction in the models studied. Considering only the energy consumption of the machining center, there is a reduction in energy consumption of 25% and 28% for machines with adapted and projected MQL system, respectively. This reduction between techniques is in accordance with the result presented by Fratila (2010) when analyzing the reduction of energy consumption in systems, in the gear milling process. The author measured a 24% reduction in energy consumption when using MQL.



Figure 10: Energy consumption per hole

When comparing the adapted and the projected MQL, an average energy consumption reduction of 2.5 to 3% is verified for the four machining conditions. This energy consumption

was not in proportion to the reduction in machining force. One explanation may be due to more powerful pumps for applying cutting fluid to the machine.

When analyzing the consumption of compressed air, the machining energy consumption increases in relation to the flood and the projected MQL has a significant reduction.

The operation of the laboratory air compressor is intermittent according to the compressed air use. When monitoring the compressed air power demand, it is possible to identify the activation time of the compression system motor (Figure 11). Thus, it is important to analyze the power demand with regular consumption without the MQL system connected and activated. The regular consumption was defined as the consumption necessary to maintain the compressed air without any equipment connected. When analyzing the it as performed in the article (Dttmann and Gomes 2019), it appears that the adapted MQL and projected MQL present a consumption of 34% and 14.75% higher than the regular consumption (Figure 12).



Figure 11: Curve of compressed air energy consumption



Figure 12: Power demand for compressed air

The results obtained in the tests are in accordance with Fratila (2010), where a reduction of 15-25% environmental impact was shown. The author also points to 25% reduction in the impact on operator health and 30% in resources.

For future studies, it is suggested to analyze the impact on the operator health when using adapted MQL, considering that during the tests execution with adapted MQL it was possible

to see fog in the external region of the machine and this could affect the operator's respiratory system.

4. Conclusion

Analyzing the results, it is possible to find the following conclusions for each observed point:

4.1. Tool life and force

Tool life in the adapted center was shorter than the designed one in all machining conditions. The reduced rigidity of the adapted system may have influenced in the reduction in tool life.

4.2. Energy consumption

Machining centers designed for MQL are more energy efficient. This can be explained by new spindles and more modern components.

Considering only the energy consumption of the machining center, there is a reduction in energy consumption of 25% and 28% for machines with adapted and projected MQL system when compared to flood, respectively.

The machining center designed for MQL had a 2.5-3% lower consumption than the adapted.

The energy models are closer to the flood technique. The difference in consumption for MQL may be related to an under-consideration of the compressed air system.

Power demand of the compressed air system in the adapted system is 17% higher than in a projected machining center for MQL use.

References

- Aramcharoen, A., and P. T. Mativenga. 2014. "Critical factors in energy demand modelling for CNC milling and impact of toolpath strategy". *Journal of Cleaner Production* 78: 63-74. https://doi.org/10.1016/j.jclepro.2014.04.065.
- Balogun, V. A., and P. T. Mativenga. 2013. "Modelling of direct energy requirements in mechanical machining processes". *Journal of Cleaner Production* 41: 179-86. https://doi.org/10.1016/j.jclepro.2012.10.015.
- Dhar, N. R., M. Kamruzzaman, and M. Ahmed. 2006. "Effect of minimum quantity lubrication (MQL) on tool wear and surface roughness in turning AISI-4340 steel". *Journal of Materials Processing Technology* 172, no. 2: 299-304. https://doi.org/10.1016/j.jmatprotec.2005.09.022.
- Diaz, N, M. Helu, and D. Dornfeld. 2010. "Design and operation strategies for green machine tool development". *The Proceedings of MTTRF 2010 Annual Meeting*. https://escholarship.org/uc/item/613797g5#main.
- Dolinšek, S., B. Šuštaršič, and J. Kopač. 2001. "Wear mechanisms of cutting tools in high-speed cutting processes". *Wear* 250: 349-56. https://doi.org/10.1016/S0043-1648(01)00620-2.
- Dttmann, A., and J. O. Gomes. 2019. "Energy consumption evaluation in machining centers adapted for MQL". Paper presented at the International Congress of Mechanical Engineering-COBEM 2019, Uberlândia, Brazil, October 2019. https://doi.org/10.26678/abcm.cobem2019.cob2019-1963.
- Ekinovic, S., H. Prcanovic, and E. Begovic. 2015. "Investigation of influence of MQL machining parameters on cutting forces during MQL turning of carbon steel St52-3". *Procedia Engineering* 132: 608-14. https://doi.org/10.1016/j.proeng.2015.12.538.
- Fratila, D. 2010. "Macro-level environmental comparison of near-dry machining and flood machining". *Journal of Cleaner Production* 18, no. 10-11: 1031-39. https://doi.org/10.1016/j.jclepro.2010.01.017.

- Fratila, D., and C. Caizar. 2012. "Investigation of the influence of process parameters and cooling method on the surface quality of AISI-1045 during turning". *Materials and Manufacturing Processes* 27, no. 10: 1123-28. https://doi.org/10.1080/10426914.2012.677905.
- Gaurav, G., A. Sharma, G. S. Dangayach, and M. L. Meena. 2020. "Assessment of jojoba as a pure and nano-fluid base oil in minimum quantity lubrication (MQL) hard-turning of Ti-6Al-4V: A step towards sustainable machining". *Journal of Cleaner Production* 272: 122553. https://doi.org/10.1016/j.jclepro.2020.122553.
- Hamran, N. N. N., J. A. Ghani, R. Ramli, and C. H. C. Haron. 2020. "A review on recent development of minimum quantity lubrication for sustainable machining". *Journal of Cleaner Production* 268: 122165. https://doi.org/10.1016/j.jclepro.2020.122165.
- He, Y., F. Liu, T. Wu, F. P. Zhong, and B. Peng. 2012. "Analysis and estimation of energy consumption for numerical control machining". *Proceedings of the Institution of Mechanical Engineers Part B-Journal of Engineering Manufacture* 226, no. B2: 255-66. https://doi.org/10.1177/0954405411417673.
- Khunt, C. P., M. A. Makhesana, K. M. Patel, and B. K. Mawandiya. 2020. "Performance assessment of vegetable oil-based minimum quantity lubrication (MQL) in drilling". *Materials Today: Proceedings*. https://doi.org/10.1016/j.matpr.2020.09.741.
- Klocke, F., and G. Eisenblätter. 1997. "Dry cutting". *CIRP Annals* 46, no. 2: 519-26. https://doi.org/10.1016/S0007-8506(07)60877-4.
- Machado, Á. R., A. M. Abrão, R. T. Coelho, and M. B. da Sillva. 2011. *Teoria da usinagem dos materiais*. 2nd ed. Blucher.
- Mori, M., M. Fujishima, Y. Inamasu, and Y. Oda. 2011. "A study on energy efficiency improvement for machine tools". *CIRP Annals-Manufacturing Technology* 60, no. 1: 145-48. https://doi.org/10.1016/j.cirp.2011.03.099.
- Özbek, O., and H. Saruhan. 2020. "The effect of vibration and cutting zone temperature on surface roughness and tool wear in eco-friendly MQL turning of AISI D2". *Journal of Materials Research and Technology* 9, no. 3: 2762-72. https://doi.org/10.1016/j.jmrt.2020.01.010.
- Rahim, E. A., and H. Sasahara. 2011. "A study of the effect of palm oil as MQL lubricant on high speed drilling of titanium alloys". *Tribology International* 44, no. 3: 309-17. https://doi.org/10.1016/j.triboint.2010.10.032.
- Ravi, S., P. Gurusamy, and V. Mohanavel. 2020. "A review and assessment of effect of cutting fluids". *Materials Today: Proceedings*. https://doi.org/10.1016/j.matpr.2020.05.054.
- Sarikaya, M., and A. Güllü. 2014. "Taguchi design and response surface methodology based analysis of machining parameters in CNC turning under MQL". *Journal of Cleaner Production* 65: 604-16. https://doi.org/10.1016/j.jclepro.2013.08.040.
- Sharma, V. S., M. Dogra, and N. M. Suri. 2009. "Cooling techniques for improved productivity in turning". *International Journal of Machine Tools & Manufacture* 49, no. 6: 435-53. https://doi.org/10.1016/j.ijmachtools.2008.12.010.
- Umbrello, D., F. Micari, and I. S. Jawahir. 2012. "The effects of cryogenic cooling on surface integrity in hard machining: A comparison with dry machining". *CIRP Annals-Manufacturing Technology* 61, no. 1: 103-06. https://doi.org/10.1016/j.cirp.2012.03.052.